

Condition Evaluation of the JFK Causeway Post-tensioned Segmental Bridge

by Brian D. Merrill, Wiss, Janney, Elstner Associates Inc.

The John F. Kennedy (JFK) Memorial Causeway Bridge, completed in 1973, carries Texas Park Road 22 over the Gulf Intracoastal Waterway (GIWW), connecting Corpus Christi to North Padre Island, Tex.

The original causeway was built in 1950 as a two-lane toll road with swing bridges across two channels. In 1973, it was replaced with a four-lane public roadway that consists of 36 prestressed concrete beam approach spans and a continuous three-span segmental unit over the GIWW. The 3280-ft-long, 60-ft-wide bridge carries two lanes in each direction. The main span continuous unit was the first precast

concrete post-tensioned (PT) segmental bridge built in the United States to carry vehicular traffic and was primarily designed by the University of Texas at Austin (UT) with assistance from the Texas Department of Transportation (TxDOT). This article reports on the thorough condition investigation and service-life modeling of the structure that was conducted in 2019 to determine rehabilitation strategies to extend the bridge's service life by at least 25 years.


Research, Design, and Construction

The project started with a TxDOT research project conducted in 1969 by Dr. John E. Breen of UT to identify a

viable concrete alternate to structural steel bridges in the 130- to 350-ft-span range. The research project identified concrete PT segmental bridges as a viable candidate based on studies of bridges recently constructed in Europe.¹ TxDOT then extended UT's contract to investigate other design and construction aspects of segmental construction in four subsequent studies: epoxies for segment joints, design and optimization studies, computer analysis, and load tests of a scale-model bridge.²⁻⁵ The studies culminated with a final report, *Minimizing Construction Problems in Segmentally Precast Box Girder Bridges*.⁶ The JFK Causeway was actually the second precast concrete segmental

The John F. Kennedy Memorial Causeway Bridge over the Gulf Intracoastal Waterway was completed in 1973. The 400-ft-long (200 ft main span with 100 ft back spans) continuous main unit was the first precast concrete post-tensioned segmental box-girder bridge built in the United States. Photo: Texas Department of Transportation.






Cantilever tendon anchor in web.



Deck tendon after excavation and opening of ducts for inspection.



Continuity tendon anchor in deck.

Typical post-tensioning anchor details as shown in original plans. Figure: Texas Department of Transportation.

surface, but no overlay was provided for the prestressed concrete beam approach spans. In the 7-in.-thick segment top slabs, the design clear cover was 1 1/8 in. for the top mat of reinforcing steel and 1 in. for the bottom mat. For the 12-in.-thick webs and the 6-in.-thick bottom slab, the interior and exterior clear covers were both 1 1/2 in.

Condition Assessment

In November 2019, a condition assessment of the main span continuous unit was performed. It included the following tasks: visually assessing 100% of the interior and exterior of both box sections; locating PT ducts using nondestructive evaluation methods to identify potential grout anomalies (for example, voids); opening selected tendons or anchorages for visual inspection and grout sampling; coring at various locations on the box girders for chloride and carbonation testing; using ground-penetrating radar to survey reinforcing bar cover; and performing half-cell corrosion potential testing. The goal of the assessment was to develop repair recommendations for a target service-life extension of at least 25 years.



Continuity tendon anchor in deck exposed for inspection.



Borescope image of small void in deck tendon near post-tensioning anchor.



Moderate corrosion of continuity tendon anchor at end of box girder.

Photographs from the condition assessment of the main span continuous unit that included visually assessing 100% of the interior and exterior of both box girders; locating post-tensioning (PT) ducts using nondestructive evaluation methods to identify potential grout anomalies; and exposing selected tendons or anchorages for visual inspection and grout sampling. The PT tendon survey indicated that the PT system was generally in very good condition. Photos: Wiss, Janney, Elstner Associates Inc.



Spalling on the exterior face of the box girder exposed corroded supplemental (not indicated in original plans) wire-mesh reinforcement with insufficient clear cover. Photo: Wiss, Janney, Elstner Associates Inc.

The exterior visual survey identified diagonal cracking in the webs that had occurred during tensioning of the cantilever tendons and had been sealed with epoxy, spalling in the pourback mortar at the end anchorages of the continuity tendons, and isolated surface spalling with exposed reinforcing steel. No distress was observed at the previously sealed web cracks, and spalling that exposed corroded reinforcing steel occurred only at locations where it appeared that supplemental (not indicated in the plans) wire-mesh reinforcement had been installed with insufficient clear cover.

The visual survey of the interior of the box girders revealed diagonal cracking at the diaphragms in the pier segments, web cracking reflecting the cracks on the exterior face of the webs, and some evidence of moisture intrusion at the deck anchorages. An important observation was that no segment joint had any evidence of leaking.

The PT tendon survey indicated that the PT system was generally in very good condition. Very few grout voids were detected, and the strands that were uncovered in the deck or box web ducts were in like-new condition. There was some evidence of regrouting, likely to fill voids left during initial grouting. No evidence of PT system distress was observed, except for moderate corrosion of the end anchors where the pourback concrete failed to protect them from the corrosive environment. No distress was observed to be associated with the moisture intrusion at the deck anchorages. It

was apparent that great care had been taken during construction to ensure the ducts were fully grouted.

Chloride ingress was evaluated at several locations on the bridge: top of deck, underside of wings, inside and outside webs, and the bottom slab. Chloride concentrations for all cored locations were well below the corrosion threshold at the level of the reinforcing steel. Clear cover of the main reinforcing steel was uniform across the box sections with little variation, except for the previously mentioned supplemental steel and isolated miscellaneous steel pieces left in the forms.

Conclusion

The condition data and the clear cover measurements were used to develop an in-house service-life model, which indicated that the structure could easily attain a 25-year service-life extension with the following treatments:

- Replacement of the asphalt overlays using a waterproofing membrane or with a polyester polymer concrete overlay
- Spot repairs to the isolated corrosion spalling
- Addition of a water-repellant coating to the exposed box-girder surfaces
- Replacement of the pourbacks at the end tendon anchorages
- Possible addition of a cathodic protection system to the substructure

The JFK Causeway Segmental Bridge is in overall good condition considering its marine-exposure environment and the lack of corrosion-mitigating features included in its original design. There were

minor occurrences of corrosion, which were mainly related to initial construction defects, but the PT system was in like-new condition.

References

1. Lacey, G. C., and J. E. Breen. 1969. *Long Span Prestressed Concrete Bridges of Segmental Construction: State of the Art*. Report 121-1. Austin: University of Texas at Austin Center for Highway Research. <https://library.ctr.utexas.edu/digitized/texasarchive/phase1/121-1-CHR.pdf>.
2. Kashima, S., and J. E. Breen. 1974. *Epoxy Resins for Jointing Segmentally Constructed Prestressed Concrete Bridges*. Report 121-2. Austin: University of Texas at Austin Center for Highway Research. <https://library.ctr.utexas.edu/digitized/texasarchive/phase1/121-2-CHR.pdf>.
3. Lacey, G. C., and J. E. Breen. 1975. *The Design and Optimization of Segmentally Precast Prestressed Box Girder Bridges*. Report 121-3. Austin: University of Texas at Austin Center for Highway Research. <https://library.ctr.utexas.edu/digitized/texasarchive/phase1/121-3-CHR.pdf>.
4. Brown Jr., R. C., N. H. Burns, and J. E. Breen. 1974. *Computer Analysis of Segmentally Erected Precast Prestressed Box Girder Bridges*. Report 121-4. Austin: University of Texas at Austin Center for Highway Research. <https://library.ctr.utexas.edu/digitized/texasarchive/phase1/121-4-CHR.pdf>.
5. Kashima, S., and J. E. Breen. 1975. *Construction and Load Tests of a Segmental Precast Box Girder Bridge Model*. Report 121-5. Austin: University of Texas at Austin Center for Highway Research. <https://library.ctr.utexas.edu/digitized/texasarchive/phase1/121-5-CHR.pdf>.
6. Breen, J. E., R. L. Cooper, and T. M. Gallaway. 1975. *Minimizing Construction Problems in Segmentally Precast Box Girder Bridges*. Report 121-6F. Austin: University of Texas at Austin Center for Highway Research. <https://library.ctr.utexas.edu/digitized/texasarchive/phase1/121-6f-chr.pdf>. 

Brian D. Merrill is a principal in the Austin, Tex., office of Wiss, Janney, Elstner Associates Inc.