



Girder end cracking that developed during the prestressing process. Photo: Wisconsin Department of Transportation.